Proposed Planned Maintenance Programme 2017/18

Location	Proposed Works	£000s	Comment/Justification	Priority
			Guttering leaking, damp penetration, rot to timber, repairs	
Alexandra Recreation Ground	Damp Proofing	30	required	1A
Auriol Pavilion	New boiler and associated works	20	Boiler condemned requires replacement	1A
-			Windows are rotten in exposed areas, external decorations	
Cox Lane Centre	External decoration and window replacement	20	required to maintain property	1A
			Repair and alter railings on staircases, fill openings in	
Ashley Centre car park	Health and Safety risks	20	staircases, Replace height restriction sign	1A
Town Hall	Upgrade controllers to BMS management system	10	Over 10 years old, parts not available any more	1A
Bourne Hall	First floor Office	7	Provide and fit air conditioning to office	1A
Cemetery Chapel	Soffits and fascias	5	External decorations to entrance of Chapel	1A
			Over 12 years since any external decorations have been	
			carried out, with new operations within building it is	
Harriers centre	Redecoration - Internal & External	15	essential we maintain the asset.	1A
Dayman Hall Ladan	Additional works requested by Building control to	,	Insulation required to first floor walls and loft as instructed	l
Bourne Hall Lodge	insulate roof	 '	by Building control Emergency repairs to walls and fences, these are raised	1A
			by public, staff, CRM's, parking and street care as they	
Various	Walls and fences	5	occur throughout the year	1A
			Emergency repairs to surfaces, car parks, parks, council	
			owned land and hard surfaces, these are raised by public,	
			staff, CRM's, parking and street care as they occur	
Various	Hard surfaces pathways, roads & car parks	20	throughout the year	1A
Regulatory works				
			Many issues found after 5 yearly electrical condition	
Various	Remedial electrical works/ 5 yearly inspections	45	reports carried out, H&S	1 _{1A}
74.7545	remedial closerous norms, a yourly inspections	 	Additional funds required to carry out repairs and	177
Various	Remedial works following Fire Risk Assessments	5	alterations following risk assessment/survey	1A
vanous	Tremedial works following the trial treesessing its	 	Minor improvements to reduce energy consumption, cost	177
			for repairs and maintenance to meters and renewal where	
Various	Energy Efficiency		necessary	1A
Various	Asbestos	10	Asbestos reinspections	1A
			Minor improvements to reduce water consumption, repairs,	
Various	Water Efficiency		water leaks, and maintenance of meters.	1A
	Total	234		